ID	Task ID	Taske name	TFM kode	Building	Fløy	Etasje nr.	Rom nr.	Rombokstav
	201560			Brussels, Office building				
201560		621 Elevator service	+112273=62.	,				
201559 200630 200629	201559	3 Leakage controll of		Brussels, Office building				
		technical systems with		, , , , , , , , , , , , , , , , , , , ,				
		refrigreant.						
	200630	332 Control of sprinkler		Brussels, Office building				
	200030	system	+=112273=33	brussels, office building				
	200629	332 Annual service of		Brussels, Office building				
	200029	sprinkler systems	+112273=33.	Brusseis, Office building				
	200628	332 Inspection of	.112273 33.	Drussals Office building				
200628	200028	sprinkler system	+112273=33.	Brussels, Office building				
200020	106272			Davida Office building				
100070	196373	262 Inspection of roof	+112273=26.	Brussels, Office building				
196373								
	196372	36 Inspection of air	+112273=36.	Brussels, Office building				
		handlings - unit / plants						
196372								
	196374	43 Control of main		Brussels, Office building				
		switchboards and						
196374		electricity distribution						
	196371	43 Inspection of main	+112273=43.	Brussels, Office building				
		switchboards and						
196371		electricity distributions						
	196369	000 Drone inspection		Brussels, Office building				
196369		·		_				
	196368	370 Inspection of	+112273=37.	Brussels, Office building				
		refrigeration systems		,				
		before the summer						
196368		season						
	196367	000 Review of fire safety		Brussels, Office building				
196367	150507	strategy		brussels, office building				
	196365	000 Measurement of		Brussels, Office building				
196365 196364	150505	radon		brussels, office building				
	196364	000 Annual protection		Brussels, Office building				
	190304	round on the property		Brusseis, Office building				
100004	100202			Drussala Office building				
	196363	31 Legionella prevention		Brussels, Office building				
106363		 System risk assessment. 						
196363	10000	442 Cartal of a consum						
40000	196362	443 Control of emergency		Brussels, Office building				
196362		lighting.						
	196361	443 Inspection og	+112273=44.	Brussels, Office building				
196361		emergency lighting						
	196360	542 Inspection of the fire	+112273=54.	Brussels, Office building				
196360		alarm system.						
	196359	100 Inspection of the		Brussels, Office building				
		evacuation routes to the						
		building in accordance						
		with the building`s						
		evacuation plan						
196359								
	196358	542 Control of fire alarm		Brussels, Office building				
196358		system.						
Sum		1-1				······································		